

## Startup and commissioning, PIX cubicles, M type, fuse contactor, CT, up to 12kV, scheduling 5X8

FSB10941

## Main

Lifecycle Service	Startup and commissioning
Period of intervention	Standard working hours
Product or component type	Installation & commissioning & startup
Zone of intervention	160 kilometers radius of a Schneider Electric services' location
Service description	Perform safety procedures Perform visual inspection of installation for proper operation Perform functional verification of correct operation including accessories Perform testing and commissioning of the switchgear Train operator (basic operation) during installation and commissioning Perform start-up of the switchgear if power available Deliver site work undersigned report as per Schneider Electric guidelines
Service benefits	Installation including connections checked with manufacturer' specifications  Mechanical, communication, electrical and electro-mechanical features checked  Whole functionalities are available and ready to be energised  Documented traceability of the delivered service

## Complementary

Product compatibility	PIX cubicle
Time to execute	5 h
Service use conditions, context and limits	Standard site and product and equipment access Geographical restrictions may apply Facilitation of site access with on-site point of contact All statutory requirements and site readiness to be completed before Schneider Electric representative visit Any civil work to be completed before Schneider Electric representative visit Manpower and requirement resources arrangement to be completed before Schneider Electric representative visit Power supply available for start-up of product Customer signs-off the completed service report Product operates in an environment that adheres to manufacturer specifications
Excluded services	Time for entrance permission Time for onsite's customer safety training or health check Trouble shooting of wrong installation Modification of civil work, anchorages or fixation Check of cables features and terminations Tests and checking other than the one's indicated above Additional service out of involved product Advanced operation and maintenance training of operator(s)
Applicable products	PIX

## **Packing Units**

Unit Type of Package 1	PCE
Number of Units in Package 1	1